

# **MOT Test Certificate**

263293819519	Vehicle Registration Mark BD08LHP		JTDKB20UX07760056		
263293619319	BD08LHP				
fake	Model		Colour		
TOYOTA	PRIUS		Blue		
ssuer's Name	Test Class		Country of Registration	1	
D. T. HEAGARTY	4		Great Britain		
Expiry Date	Issued		Test Station		
21 August 2018 (EIGHTEEN)	22 Aug 2017		77882		
Odometer Reading and History		Inspection Author	itv		
22 8 2017: 256498 mi 8 8 2016: 223937 mi 28 7 2015: 192754 mi 7 8 2014: 165256 mi		CENTRAL GARA 31-35 OLD TIV EXETER EX4 6LG	SE SERVICES EXETER LTD FERTON ROAD 01392 428088	. 4	
Additional Information		Signature of Issue	er /		
Advisory Information  001 Windscreen has damage to  002 Front (wipers poorly clea	aring screen) V	40mm circle ours	Ide z ne A [B.B.1d] MOTCR WORKS 01392		
003 Rear (registration plate 004 Front (headlamp lenses de 005 Nearside Front (tyre wear	eteriorating resulti ring on outer edge)		·46-46-43		
003 Rear (registration plate	eteriorating resulti ring on outer edge)	Terred	·46-46-43		

## About this document

- 1 This document is a receipt style certificate telling you that an MOT Test pass result has been recorded in the Driver & Vehicle Standards Agency's (DVSA's) database of MOT Test results; this can be verified at www.gov.uk/check-mot-status.
- 2 A test certificate relates only to the condition of the components examined at the time of test. It does not confirm the vehicle will remain roadworthy throughout the validity period of the certificate.

  3 Check carefully that the details are correct.

- Whilst advisory items listed above do not constitute MOT failure items, they are drawn to your attention for advice.

  5 For further information about this document, please visit www.gov.uk/getting-an-mot or contact DVSA on 0300 123 9000\*.
- \*Your call may be monitored or recorded for lawful purposes.

# Comprehensive Vehicle Inspection Report

**Customer Details** 

Report Date: 22/08/17

Report No: 10421

**Exeter Motor Works Old Tiverton Road** 

Exeter

Customer's contact details

Home:

Work: 01392 210739

Mobile: 07810825111

VEHICLE DETAILS

Make

TOYOTA

Registration Number

BD08 LHP

Model

PRIUS T3 VVT-I

Colour Blue

Vehicle Identity Number (VIN)

JTDKB20UX07760056

VIN Checked and confirmed

on vehicle Yes X No

V5/Registration document

available and checked

No

MOT Certificate available and

Yes

Mileage reading

In

256502

**MOT Expiry Date** 

checked

21/08/18

(Not guaranteed)

Out

256498

Vehicle Excise Licence Expiry

01/05/18

Date of inspection

22/08/17

Time of inspection

16:00

18

Location of vehicle

Exeter Motor Works, Old Tiverton Road, Exeter.

Lighting

Good

Weather. (See notes) Good

Ramp available. (See notes)

Yes ☐ No ☒

SECURITY CHECK

The vehicle identification number on this vehicle was checked and found to be consistent with the manufacturer's format.

SUMMARY REPORT


READY FOR USE - No faults found, suitable for immediate use.

ADVISABLE REPAIRS ONLY - Suitable for immediate use but advisable repairs should be planned for.

ESSENTIAL AND ADVISABLE REPAIRS REQUIRED - Not suitable unless all essential repairs are undertaken and advisable repairs, if any are planned for.

UNSATISFACTORY - Vehicle has significant deficiencies, which are judged to be impractical or uneconomical to repair to a satisfactory standard.

Please read all pages of this report



Minor blemishes, which are acceptable fair wear and tear for the vehicle's age, recorded mileage and type, are not recorded and you should satisfy yourself in this regard.

EVIDENCE OF BODYWORK REPAIRS Yes X No

BODYWORK CLEAN AND DRY

Yes X No (See Notes)

### Comments

The exterior body condition was good and commensurate with the vehicles age and recorded mileage.

KEY FOR	POINTS ON FOLLOWING PAGES *
s	Satisfactory for age and recorded mileage
	Could not be checked
x	Essential repair requiring immediate attention
Α	Advisable repair should be considered prior to purchase
N/A	Not applicable
Y	Yes
N	No
	Please note: Right = Off side (O/S) and Left = Near side (N/S) as viewed from the driver's seat.

Report No: 10421

pers / No plates – Ft / Rr	S	Body damage     Corrosion	S No	14. Bonnet hinges No	S
7	۸		0	ALEX SECTIONS STREET	0
trim /grille	S	8. Soft top / Hard top (operation)	N/A	13. Bonnet catch	2
4	S	<ol><li>Fuel filler cover and cap</li></ol>	S	<ol><li>Body panels</li></ol>	S
ition / alignment	Α	6. Door locks - operation	S	11. Mud flaps	S

NGINE COMPARTMENT	PETR	ROL DIESEL MULTI-FUE	EL 🗌	No. of CYLINDERS: 4	
15. Coolant Level / Condition	S	22. Power Steering - oil level	S	29. Turbo / supercharger	-4
16. Coolant leaks	No	23. Clutch Fluid	S	30. Fuel pump / pipes	S
17. Antifreeze *	S	24. Brake Fluid	S	31. Accelerator linkage	S
18. Radiator / Cap	S	25. Engine Oil level	S	32. Cold starting	
19. Hoses / Pipes	S	26. External leaks (upper engine)	S	33. Fast idle (cold)	
20. Drive Belts		27. Engine mountings	S	34. Noise level (cold)	
21. Water Pump (Not visible)		28. Fuel Injection	S	35. Excess fumes / smoke	No

Note - To ensure future serviceability, it is important that the engine camshaft belt is replaced at intervals specified by the manufacturer. It is in your best interests you ensure that this is carried out. \* Antifreeze only has a 2/3 year life span and requires its strength adjusting after this time or replacing as per manufacturers specifications.

ELECTRICAL / CONTROLS					
36.Starting system / Ignition lock	S	41. Rear lights & No. plate lights	S	49. Instruments	S
37. Battery condition	S	42. Stop lights	S	50. Horn	S
38. Battery voltages:	S	43. Indicator/ Hazard lights	S	51. Radio/Cass/CD/Aerial	S
- Normal 12.80 volts	S	44. Reverse / Fog lights	S	52. Heater / Fan controls	S
- Starting 10.55 volts	S	45. Auxiliary lights	N/A	53. Air Con operation	S
- Charging 14.40 volts	S	46. Interior / Panel lights	S	54. Windows / Sun roof	S
39. Headlights	S	47. Mirrors (electric)	S	55. Wipers / Washers	S
40. Sidelights / running lights	S	48. Controls / Switches	S	56. Headlamp wash / wipe	N/A

**Note** - We are unable to verify dash panel light and switch back lighting operation due to the daylight conditions. Please note that switching them "on or off" only assesses electrical components. Accuracy of instruments cannot be assessed.

INTERIOR / LUGGAGE COMP	PARTI	MENT		NUMBER OF SEATS: 5	
57. Steering Wheel / Adjustment	S	64. Door seals / hinges	S	71.Rear parcel shelf / load cover	
58. Seat upholstery	S	65. Interior sills	S	72. Boot / tailgate lock	S
59. Seat adjustment	S	66. Headlining / visors	S	73. Luggage area trim con	S
60. Seatbelts	S	67. Sun roof	N/A	74. Illumination light	S
61. Carpets / Mats	S	68. Dash panel (condition)	S	75. Tool kit	S
62. Door trim panels	S	69. Cigarette lighter	N/A	76. Hard / Soft top (condition)	N/A
63. Door fittings / operation	S	70. Mirrors (internal)	S	77. Tonneau cover	N/A

FRONT SUSPENSION / STE	ERING /	UNDER FRAME			
78. Engine underside leakage	No	83. Wheel hubs / bearings	S	88. Sub-frames mountings	S
79. Steering joints/ ball joints	S	84. Springs/suspension units	S	89. Suspension arms / mountings	S
80. Steering rack / box	S	85. Pipes / hoses	S	90. Tie bars / anti roll bars	S
81. Chassis members	S	86. Dampers (condition / leaks)	S	91. Corrosion protection	Yes
82. Power steering (operation)	S	87. Gaiters	S	92. Corrosion - floor/chassis	No

REAR SUSPENSION / UND	ER FRAN	/IE			
93. Springs/suspension bars	S	97. Location rods/fixings	N/A	101. Sub-frames/ mountings	S
94. Anti roll bar	S	98. Bump stops/gaiters	N/A	102. Chassis members	S
95. Dampers/bushes	S	99. Wheel hubs/bearings	S	103. Corrosion protection	Yes
96. Suspension arms/fixings	N/A	100. Pipes/hoses	N/A	104. Corrosion - floor/chassis	No

CLUTCH / TRANSMISSION	MANU	JAL AUTOMATIC 🖂	MULTI-U	ISE / 4x4	
105. Fluid / oil leaks	No	109. Casings	S	113 Backlash	S
106. Cables / adjustments	N/A	110. Mountings	S	114. Gaiters	S
107. Hydraulic system	S	111. Drive shaft assembly	S	115. Propshaft(s) / fittings	N/A
108. Linkage (wear)	S	112. Universal / sliding joints	S	116. Bearings / supports	N/A

ystem  Nytic converter (s)	S S	120. Silencer(s) 121. Heat shields / mountings 122. Joints / couplings	SSS	123. System condition	S
----------------------------	--------	--	-----	-----------------------	---

4. Tank 125. Tank fixings	S S	126. Fuel lines 127. Breather pipes	S	128. Evidence of leaks	No
------------------------------	--------	--	---	------------------------	----

BRAKES			
30. Fluid leaks No 133.	Flexible hoses S Pipes / connections S Discs / pads (if visible) S	135. Handbrake op / adjustment 136. Handbrake mechanism 137. Pedal and pad / linkage	S

Note - If the vehicle is fitted with brake drums the internal parts including linings are not visible. Brake fluid should be replaced at the manufacturers specifed intervals.

It is recommended ty	RES Type: Alloy res be replaced when the result in excessive and r	e tread depth reaches rapid tyre wear. A full	2mm. If uneven tyre wear is noted, t steering and geometry check is reco	this may indicate i	ncorrec
138. Wheel Rims 139. Wheel Trims	S S				
Tyres 140. Front RH 141. Front LH 142. Rear LH 143. Rear RH 144. Spare	Make Kumho Autogrip Autogrip Autogrip Bridgestone	Size 195/55/16 195/55/16 195/55/16 195/55/16 125/70/16	Type / Construction Radial Radial Radial Radial	Min tread 6.5mm 5.5mm 5.5mm 4.5mm	S S S

### 145. ROAD TEST

The road test has been undertaken within the speed limits and prevailing traffic conditions in the locality of the inspection. If a road test has not been carried out, please refer to the engineer's comments page.

\*If the vehicle is fitted with 4wd transmission then the systems have been checked for security, leakage and excessive noise. However, within the limitations of the road test the full functionality could not be checked.

Test Distance 3 Miles		Speed achieved up to 40 I	МРН		
146. Final drive operation / Noise level	S	153. Instrument /controls function	No	160. Road holding / stability	S
<ol> <li>Gearbox operation / Noise level</li> </ol>	S	154. Steering wheel alignment	S	161. General steering / handling	S
148. Engine performance 149. Engine noise 150. Excess smoke 151. Overheating evidence	S S No No	155. 4WD operation * 156. Clutch operation ** 157. Cooling fan operation 158. Steering effort	N/A S S	162. Footbrake operation 163. Hand/park brake operation 164. Suspension noise 165. Warning lights	S S No
152. Auto changes / kick-down	N/A	159. Hot restarting	S	166. Cruise control	S

\*\* It should be carefully noted that the life expectancy of clutches is uncertain and difficult to predict, being dependant on owners driving style, vehicle operation and terrain. The fact that the clutch has not been identified as faulty/slipping/juddering/noisy on the report does not and should no be taken to imply that the clutch assembly will have a continuing life expectancy from the time of our check. They can begin to slip at any time.

FINAL CHECK					
167. Oil leaks	No	168. Coolant leaks	No	169. Uneven tyre wear	
		I Tourio	140	109. Offeven tyre wear	No

Report No: 10421

# Éngineers Comments

The vehicle is considered overall to be a fair and reasonable example of the type, being in a generally reasonable condition and generally considered to be consistent with the type for the age and indicated recorded mileage in most areas.

The items listed as "could not be checked" (---) normally indicate items were obscured by covers/shields or other equipment.

The Water pump – Engine drive belt/chain - these items could not been fully examined, as covers, trims and other equipment obscure them.

The cooling system was pressure tested to 0.7 bars, no pressure loss was noted on the system or pressure cap. The antifreeze concentration was an acceptable, but has deteriorated from its original strength and at the next routine service may need to be refreshed/replaced. It is advised that the coolant strength be checked again at the next routine service. Antifreeze only has a 2/3-specifications.

The vehicle is fitted with vented front brake disc and pads, supported at the rear by a single arrangement. Although the visible brakes only show some signs of general serviceable wear, some deterioration is noted, which will need attention in the near future. It is strongly advised to remove all road wheels and examine the inner brake components, which are obscured on this vehicle prior to purchase, replacing any worn or badly corroded parts. It is probable that the front brakes at least, will need to be replaced at the next routine service.

The braking system's fluid contains the presence of some water/condensation in the system. It is recommended that the fluid content is completely replaced at the next service interval.

The steering & suspension has been assessed to MOT standard. This allows for a degree of wear and deterioration of components without rendering them unserviceable. The extent of wear is not considered excessive at this juncture and unlikely to attract MOT failure.

The road test distance and or top speed was limited due to the general area/inspection location, and/or traffic levels and/or adverse weather conditions and/or lack of fuel when the vehicle was tested and driven. Comment cannot be made in these instances in relation to possible "high stage after any purchase due to these limiting conditions.

ssential Repairs

ι is strongly advised that the essential defects are investigated and rectified prior to purchase.

Item Comment

## Additional Comments

No vehicle hoist/ramp was available. A large trolley jack and stands were used in order to carry out underside checks. This limits the view of the underside somewhat. Some areas could not be fully seen. There may be further defects, which may be visible given clear underside access and view.

The exhaust has been identified, as having limited life because, although there is no leakage present, there is some external corrosion present and the inside of the system, which may have significant deterioration, cannot be inspected internally.

Please note that a service is recommended, this may reveal repairs or maintenance requirements that could not be identified due to the constraints of a visual and external examination of the vehicle carried out without the benefit of a vehicle hoist.

Report No: 10421

dvisable Repairs

Please note that the advisable items may prove costly to repair, and must be considered.

#### Comment

- NSR Door has some damage, but does not affect it's operation. 01
- Windscreen has some damage, but does not obscure the Driver's vision.

The engineer was unable to verify dash panel light and switch back lighting operation due to the daylight conditions. Please note that switching them "on or off" only assesses electrical components. Accuracy of instruments cannot be assessed.

Although the radio operates when switched on, the full functionality of the in-car entertainment system has not been checked. This is beyond the scope of our inspections. You should ask the vendor to fully demonstrate the systems before purchase.

Report No: 10421

- You are strongly advised to discuss the findings of this report with the vendor prior to PLEASE READ CAREFULLY making your decision to purchase the vehicle.
  - Essential repairs should be investigated and rectified prior to purchase. These may be
  - Advisable repairs may prove costly to repair and must be considered prior to purchase.

Engineer's Name

Phillip Bailey

Qualifications

BSc Hons), M.I.M.I, AAE.