

APPENDIX C


MOT and HISTORY

MOT test certificate

① Vehicle identification number

WF0WXXGCEWGC73409

② Registration number



③ Country of registration

GB

Make and model

FORD GRAND C-MAX

④ Vehicle category

M1

⑤ Mileage

236,279 miles

Mileage history

204,933 miles

14.10.2024

175,269 miles

05.10.2023

135,353 miles

03.10.2022

① Pass

⑥ Date of the test

17.09.2025

⑦ Expiry date

14.10.2026

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 15.09.2026.

⑧ Location of the test

UNIT 3 CITY INDUSTRIAL ESTATE, MICHAEL BROWNING WAY, EXETER, EX2 8DD

⑨ Testing organisation and inspector name

**S002853 QUAYSIDE MOT AND TYRE
S. N. Bulley**

MOT test number

9994 5063 6087

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.



Driver & Vehicle
Standards
Agency

Issuer signature

Check MOT history

Help us make this service better. Give us your [feedback](#).

[Back](#)

There's an outstanding recall on FORD GRAND C-MAX SX16CTF

If you're the owner or driver of this vehicle, contact your nearest FORD dealership for information and to arrange a free repair.

Continue to MOT History

Date tested
17 September 2025

PASS

Mileage
236,279 miles

Test location
[View test location](#)

MOT test number
9994 5063 6087

Expiry date
14 October 2026

Date tested
8 September 2025

FAIL

Mileage
234,941 miles

Test location
[View test location](#)

MOT test number
7895 5356 1786

- Repair immediately (major defects):
- Windscreen in an unacceptable condition windscreen damaged more than 10mm diameter in zone A (3.2 (c) (i))
 - Nearside Headlamp light source and lamp not compatible LED bulb fitted (4.1.4 (c))
 - Offside Headlamp light source and lamp not compatible LED bulb fitted (4.1.4 (c))

- Repair as soon as possible (minor defects):
- Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

- Monitor and repair if necessary (advisories):
- Coolant leak

[What are defects and advisories?](#)

P053 MOT HISTORY

Date tested
14 October 2024

PASS

Mileage
204,933 miles

Test location

► [View test location](#)

MOT test number
9345 3582 6560

Expiry date

14 October 2025

Date tested
14 October 2024

FAIL

Mileage
204,933 miles

Test location

► [View test location](#)

MOT test number
6623 5058 8795

Repair immediately (major defects):

- **Nearside Front Position lamp not working (4.2.1 (a) (ii))**
- **Nearside Front Suspension arm ball joint excessively worn lower arm ball joint (5.3.4 (a) (i))**

Monitor and repair if necessary (advisories):

- **Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement lower arm rear bush (5.3.4 (a) (i))**

► [What are defects and advisories?](#)

Date tested
10 October 2024

FAIL

Mileage
204,601 miles

Test location

► [View test location](#)

MOT test number
9165 0897 6795

Repair immediately (major defects):

- **Nearside Front Position lamp not working (4.2.1 (a) (ii))**
- **Front Headlamp light source and lamp not compatible both sides (4.1.4 (c))**
- **Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**
- **Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**
- **Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**

Repair as soon as possible (minor defects):

- **Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**

Monitor and repair if necessary (advisories):

- **Offside Rear Child Seat fitted not allowing full inspection of adult belt**
- **Items removed from driver's view prior to test dash cam**
- **Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**

P053 MOT HISTORY

Date tested
5 October 2023

PASS

Mileage
175,269 miles

Test location
▶ [View test location](#)

MOT test number
1183 1121 9715

Expiry date
14 October 2024

Date tested
3 October 2022

PASS

Mileage
135,353 miles

Test location
▶ [View test location](#)

MOT test number
1655 2932 7053

Expiry date
14 October 2023

Date tested
30 September 2021

PASS

Mileage
99,421 miles

Test location
▶ [View test location](#)

MOT test number
8201 5079 0745

Expiry date
14 October 2022

Date tested
13 October 2020

PASS

Mileage
68,475 miles

Test location
▶ [View test location](#)

MOT test number
7467 7282 6771

Expiry date
14 October 2021

Date tested
15 October 2019

PASS

Mileage
57,253 miles

Test location
▶ [View test location](#)

MOT test number
4162 5248 8507

Expiry date
14 October 2020

Monitor and repair if necessary (advisories):

- **Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**
- **Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**

▶ [What are advisories?](#)

Date tested
8 April 2019

PASS

Mileage
47,820 miles

Test location
▶ [View test location](#)

MOT test number
2818 9516 3591

Expiry date
7 April 2020

P053 MOT HISTORY

Date tested
5 April 2019

FAIL

Mileage
47,819 miles

MOT test number
5111 3623 3713

Test location

► [View test location](#)

Repair immediately (major defects):

- **Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**
- **Front Windscreen washer not working (3.5 (a))**

Monitor and repair if necessary (advisories):

- **Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**