

VEHICLE EXAMINATION REPORT

YOUR ATTENTION IS DRAWN TO THE TERMS AND CONDITIONS BELOW

The examination of the vehicle described in this report was of a purely external, visual nature and excludes any dismantling. No responsibility can be accepted for defects not visibly present at the time, or those not detected which fall outside the scope of the examination and (where possible) its limited road test. Road tests, when possible, are conducted for a limited duration and exclude high speed testing.

The accuracy of the instrumentation within the vehicle (speedometer, odometer, fuel and temperature gauges etc.), cannot be verified, neither can the future life expectancy of the clutch and brake linings, or the failure of mechanical components in the future. Statements on fuel and oil consumption levels will also be excluded.

Report No: TOP004 Customer Details Mr. T Goode 21 Venny Bridge Pinhoe Exeter Devon Telephone: 07967 879090	Inspection Date: 19-08-2015 Inspection Address Top Marques Pinhoe Exeter Devon EX4 8JN Telephone: 01392 464640
---	---

VEHICLE DETAILS

Make & Model	Toyota Prius	Registration No.	T10ODE
Colour	Black	Engine CC	1497 (approx)
Vehicle Identity Number. (VIN No.)	JTDKB20U407564484		Confirmed Yes
Engine No: 1NZ4310934			
V5 Registration doc checked	YES	MOT Certificate Expires	18-08-2016
Odometer Reading	287964 Miles	Service Records Seen	Yes

MECHANIC SUMMARY

PLEASE READ ALL THE PAGES OF THE REPORT


Front nearside tyre close to limit
 Exhaust will need replacing soon
 EMS Light on

TOP ✓ MARQUES

EXTERIOR PANELS

KEY:

A acceptable
 G good
 R repaired
 = scratch
 X dent
 C corrosion
 O chip / rust
 D decals
 P poor condition
 -- not checked



Taxi Colour: Black SELECT

TOP ✓ MARQUES

Minor blemishes, which are acceptable for the vehicle's age and type, are not recorded and you should satisfy yourself in this regard.

EVIDENCE OF BODYWORK REPAIRS **NO** No Major Repairs seen

Comments

KEY FOR POINTS ON FOLLOWING PAGES

- S** **Satisfactory for age and recorded mileage**
- **Could not be checked**
- x** **Needs immediate attention**
- A** **Advisable repair**
- N/A** **Not applicable**
- Y** **Yes**
- N** **No**
- C** **See Engineer's comments**

BODY EXTERIOR

1. Panel Condition/Alignment	S	5. Bumpers No plates – F/R	S	9. Body damage	N
2. Paintwork	S	6. Door locks – operation	S	10. Corrosion	N
3. Exterior trim	S	7. Fuel filler cover and cap	S	11. Mud flaps None Fitted	N/A
4. Glass	S	8. Elevating Roof (operation/cond..)	N/A	12.	

ENGINE COMPARTMENT Diesel

13. Coolant Level/Condition	S	21. Clutch Fluid	N/A	29. Accelerator linkage	S
14. Coolant leaks	N	22. Brake Fluid	S	30. Body panels	S
15. Antifreeze	S	23. Engine Oil level	S	31. Bonnet catch	S
16. Radiator/Cap	S	24. External leaks (engine)	NO	32. Bonnet hinges	S
17. Hoses/Pipes	S	25. Engine mountings	S	33. Cold starting	S
18. Drive Belts	S	26. Fuel Injection	S	34. Fast idle (cold)	S
19. Water Pump	S	27. Turbocharger	S	35. Noise level (cold)	S
20. Power Steering	S	28. Fuel pump/Pipes	S	36. Excess fumes/smoke	NO

Spark plugs, Injectors or Glow Plugs are not removed.

It should be noted that a gas analyser has not been used to check exhaust emissions.

If no documentation is seen indicating camshaft drive belt replacement, to ensure future serviceability, it is important that the belt is replaced immediately and then at intervals specified by the manufacturer. It is in your best interests that you ensure that this is carried out.

TOP ✓ MARQUES

ELECTRICAL / CONTROLS					
37. Starting system/Ignition lock	S	43. Stop lights	S	51. Horn	S
38. Battery charging system	S	44. Indicator/Hazard lights	S	52. Radio/Cass./CD/Aerial	S
39. Voltages at battery:	S	45. Reverse / Fog lights	S	53. Heater(s) / Fan controls	S
normal	S	46. Auxiliary lights	S	54. Air Con operation	S
charging	S	47. Interior / Panel lights	S	55. Door locking	S
40. Headlights	S	48. Screen dimisters SELECT	S	56. Windows	S
41. Sidelights /Running lights	S	49. Mirrors (electric)	S	57. Wipers/Washers	S
42. Rear and No. plate lights	S	50. Controls/Instruments	S	58. Headlamp washers	N/A

INTERIOR / LUGGAGE COMPARTMENT					
59. Steering Wheel/Adjustment	S	66. Door seals /hinges	S	73. Rear parcel shelf/blind	S
60. Seat upholstery – F/R	S	67. Interior sills	S	74. Boot/tailgate lock	S
61. Seat adjustment	S	68. Headlining/visors	S	75. Luggage/Load area trim con	S
62. Seatbelts – F/R	S	69. Sun roof(s) Elec.	N/A	76. Illumination light	S
63. Carpets – F/R	S	70. Dash panel (condition)	S	77. Tool kit etc	S
64. Door trim panels	S	71. Cigarette lighter(s)	N/A	78. Living Area (Visual Only)	N/A
65. Door fitting /operation	S	72. Mirrors (internal)	S	79.	

FRONT SUSPENSION / STEERING / UNDERFRAME					
80. Engine underside leakage	NO	85. Wheel hubs/bearings	S	90. Sub-frames/mountings	S
81. Steering joints/ball joints	S	86. Springs/suspension units	S	91. Suspension arms/mountings/joint	S
82. Steering Rack and Pinion	S	87. Sphers/Pipes/Hoses	N/A	92. Tie bars/anti roll bars	S
83. Chassis members	S	88. Dampers (condition / leaks)	S	93. Corrosion protection	S
84. Power steering Hydraulic	S	89. Power steering pipes/gaiters	S	94. Corrosion – floor/chassis	NO

REAR SUSPENSION / UNDERFRAME					
95. Springs/suspension bars	S	99. Location rods/fixings	S	103. Sub-frames/mountings/axles	S
96. Anti roll bar	S	100. Bump stops/gaiters	S	104. Chassis members	S
97. Dampers/bushes	S	101. Wheel hubs/bearings	S	105. Corrosion protection	S
98. Suspension arms/fixings	S	102. Spheres/Pipes/Hoses	N/A	106. Corrosion – floor/chassis	NO

CLUTCH / TRANSMISSION Automatic Gearbox					
107. Fluid/Oil leaks	NO	111. Casings/Axles/Differential(s)	S	115. Backlash	S
108. Cables/adjustments	N/A	112. Mountings	S	116. Gaiters	S
109. Hydraulic system	S	113. Drive shaft assembly	S	117. Propeller shaft(s)	N/A
110. Linkage (wear)	S	114. Universal/sliding joints	S	118. Prop. Bearings/Supports	N/A

EXHAUST SYSTEM					
119. Manifold(s)	S	121. Silencer(s)/Catalyst(s)	S	123. Joints/Couplings	S
120. Pipes	A	122. Heat shields/Mountings	S	124. System condition	Limited Life

FUEL SYTEM					
125. Tank	S	127. Fuel lines	S	129. Evidence of leaks	NO
126. Tank fixings	S	128. Breather pipes	--	130.	N/A

TOP ✓ MARQUES

BRAKES

131. Master cylinder security	S	134. Flexible hoses	S	137. Hand/Parkbrake op/adjustment	S
132. Fluid leaks	N	135. Pipes/Connections	S	138. Hand/Parkbrake linkage	S
133. Servo/Power system	S	136. Discs/Pads/Drums	S	139. Pedal/Linkage	S

WHEELS AND TYRES Type

140. Wheel Rims	S	Alloy Wheels			
141. Wheel Trims	N/A				
Tyres	Make	Size	Type / Construction	Min tread depth	
142. RH Front	Sunny	195/55/16	Radial/Tubeless	4-5mm	S
143. LH Front	Sunny	195/55/16	Radial/Tubeless	2-3mm	S
144. RH Rear	Fullrun	195/55/16	Radial/Tubeless	8-9mm	S
145. LH Rear	Fullrun	195/55/16	Radial/Tubeless	8-9mm	S
146.					
147.					
148. Spare	Space Saver				

ROAD TEST

Finish Odom. Reading	287970 Miles	Conditions	Damp
Test Duration	5.9 Miles	Speed achieved up to	40 M.P.H.

149. Final drive op./Noise level	S	156. Instrument/Controls function	S	163. Road holding/Stability	S
150. Gearbox operation/noise level	S	157. Steering wheel alignment	S	164. General steering/Handling	S
151. Engine performance	S	158. Clutch operation	S	165. Footbrake operation	S
152. Engine noise	S	159. 4WD operation	N/A	166. Hand/Parkbrake operation	S
153. Excess smoke	NO	160. Cooling fan operation	--	167. Suspension noise	N
154. Overheating evidence	NO	161. Steering effort	S	168. Warning lights	S
155. Auto changes/Kickdown/Inhib.	S	162. Hot restarting	S	169.	

FINAL CHECK

170. Oil leaks	NO	171. Coolant leaks	NO	172.	
----------------	----	--------------------	----	------	--

Please read all pages of this report

TOP ✓ MARQUES


Essential & Desirable Repairs

It is strongly advised that the essential defects are investigated immediately or rectified prior to purchase of the vehicle and desirable repairs are carried out in the near future. Some defects may prove costly to rectify and this must be considered prior to purchase or authorising any remedial work.

Attention

Some vehicles are provided with a master key, which can be extremely costly to replace (sometimes in excess of £1000) as, in some cases, if the master key is missing the Engine Control Unit (ECU) may have to be replaced should you encounter problems. As well as this, some radios have codes to allow them to operate. Please satisfy yourself that you have all relevant keys and codes. You should also ensure you are given all relevant instruction manuals for the vehicle, radio, alarm and immobilisers as necessary

Item	Defect/Item requiring further investigation /rectification	D/X
------	--	-----

Report Ref:	Reg. No:	Signed:	Mechanics Name:	Date:
TOP004	T10 ODE		Dave Carter	19-08-2015