

APPENDIX A

MOT Test Certificate

on Mark Vehicle Identification Number		
WV2ZZZ2KZAX097106		
Colour FE TDI 104 Silver		
Country of Registration Great Britain		
Test Station		
Inspection Authority		
CENTRAL GARAGE SERVICES EXETER LTD 31-35 OLD TIVERTON ROAD EXETER EX4 6LG 01392 428088		
Signature of Issuer		
F		

Advisory Information

003	1 Shock absorber has a light misting of oil offside front [2.7.3] 2 Road wheel with a slightly distorted bead rim nearside front inner [4.2.A.la] 3 (front brake discs worn) 4 (no density recorded in smoke test)	

About this document

- 1 This document is a receipt style certificate telling you that an MOT Test pass result has been recorded in the Driver & Vehicle Standards Agency's (DVSA's) database of MOT Test results; this can be verified at www.gov.uk/check-mot-status.
- 2 A test certificate relates only to the condition of the components examined at the time of test. It does not confirm the vehicle will remain roadworthy throughout the validity period of the certificate.
- 3 Check carefully that the details are correct.
- 4 Whilst advisory items listed above do not constitute MOT failure items, they are drawn to your attention for advice.
- 5 For further information about this document, please visit www.gov.uk/getting-an-mot or contact DVSA on 0300 123 9000*.
- *Your call may be monitored or recorded for lawful purposes.