


VEHICLE INSPECTION REPORT HACKNEY CARRIAGES



Make SKODA	Model OCTAVIA	Reg.No. FX63MOU	Plate No.
Rec. Mileage 101020	Date 16/05/18	Petrol/Diesel	CC (Must be over 1300cc)

Testable item	Pass	Fail	Testable item	Pass	Fail	Testable item	Pass	Fail
Rear view mirrors	/	/	O/S/R tyre wall/size/valve fit	/	/	O/S/F wheel condition	/	/
Driver's seat and back rest	/	/	O/S/R wheel security/condition	/	/	O/S/F wheel bearing condition	/	/
Note recorded miles of speedo			O/S fuel cap	/	/	O/S/F drive shaft/CV joint	/	/
Front passenger seat/back rest	/	/	O/S/R shock absorber	/	/	O/S/F suspension cond/security	/	/
Both doors/internal security	/	/	Rear tail gate/boot/door security	/	/	N/S/F tyre wall/fit/tread	/	/
Steering wheel/mechanism/condition	/	/	Rear floor/belt mtgs/shock abs.mtgs	/	/	N/S/F wheel condition	/	/
Power Steering (if fitted) ◆	/	/	Tail lights condition/operation	/	/	N/S/F wheel bearing condition	/	/
Servo operation (if fitted) ◆	/	/	Stop/fog lights condition/operation	/	/	N/S/F drive shaft/CV joint	/	/
Footbrake operation/condition	/	/	Indicators condition/operation rate	/	/	N/S/F suspension cond/security	/	/
ABS system warning light (if fitted)	/	/	Hazard warning operation/rate	/	/	Lock to lock checks (turn plates)	/	/
Handbrake operation/condition	/	/	Number plate lights and reflectors	/	/	Suspension check-Shake O/S wheel	/	/
Light switches/warning lights	/	/	Number plate condition/spacing	/	/	Suspension check-Shake N/S wheel	/	/
Screen wipers/washers operation	/	/	Hackney plate-exterior ☒	/	/	O/S/R tyre wall/fit/tread	/	/
Windscreen condition/vision	/	/	Exterior advertising ☒	/	/	O/S/R wheel condition	/	/
Horn control/operation	/	/	N/S/R s/absorber & body damage	/	/	O/S/R wheel bearing condition	/	/
Belt Requirements front/3 rear ☒	/	/	N/S fuel cap	/	/	O/S/R drive shaft/CV joint	/	/
Belt condition/operation/anchorage	/	/	N/S/R tyre wall/size/valve fit	/	/	O/S/R suspension cond/security	/	/
Interior Light	/	/	N/S/R wheel security/condition	/	/	N/S/R tyre wall/fit/tread	/	/
Door catches/door/window ☒	/	/	N/S/R door security/rear back rest	/	/	N/S/R wheel condition	/	/
Fire extinguisher ☒	/	/	N/S/R out-in sills/floor/belt mountngs	/	/	N/S/R wheel bearing condition	/	/
Excise licence – current	/	/	N/S/R door security/ext.mirror	/	/	N/S/R drive shaft/CV joint	/	/
Foot pedal rubbers	/	/	N/S/F out-in sills/floor/belt mountngs	/	/	N/S/R suspension cond/security	/	/
First Aid Kit ☒	/	/	N/S repeater lamp condition (if fitted)	/	/	O/S/F brake components cond/leak ◆■	/	/
Vehicle interior including boot ☒	/	/	N/S/F tyre wall/size/valve fit	/	/	Front chassis members/suspension	/	/
Hackney No. Interior badge ☒	/	/	Ball joint/wheel security/condition	/	/	N/S/F brake components cond/leak ◆■	/	/
Meter operation	/	/	N/S wiper blade cond/screen cond	/	/	Mid chassis members/suspension	/	/
Tariff card ☒	/	/	N/S/F shock absorber	/	/	O/S structure/pipes/cables/hoses ◆■	/	/
Vehicle exterior .inc.cleanliness ☒	/	/	Under bonnet brake system/mtgs.	/	/	O/S/R brake components con/leak ◆■	/	/
Roof Sign -	/	/	Pipes/hoses/masr cylinder/servo ◆	/	/	R/chassis members/susp/tank/carrier	/	/
Number plate condition/spacing	/	/	Handbrake mechanism	/	/	N/S/R brake components cond/leak ◆■	/	/
Side-H/lamp type/condition/operation	/	/	Suspension mounts/cond/corrosion	/	/	N/S structure/pipes/cables/hoses ◆■	/	/
Indicators condition/operation/rate	/	/	Battery security/VIN No.			Exhaust cond/leaks/prop shaft	/	/
Hazard warning operation/rate	/	/	Fuel system leakage ◆	/	/	H/brake mechanism/linkage/cables ◆	/	/
Headlamp condition/aim (use equip)	/	/	Exhaust system leaks ◆	/	/	O/S/F footbrake perform. check	/	/
O/S/F s/absorber & body damage	/	/	Servo vacuum hose (if fitted) ◆	/	/	N/S/F footbrake perform. check	/	/
O/S/F tyre wall/size/valve fit	/	/	PAS pump drive pipes(if fitted) ◆	/	/	Both front brake balance check	/	/
Ball joint/wheel security/condition	/	/	Diesel pump-pipes-cambelt-oil level	/	/	Handbrake O/S perform. check	/	/
O/S wiper blade cond/screen cond	/	/	Steering components (rock str wheel)	/	/	Handbrake N/S perform. check	/	/
O/S repeater lamp condition (if fitted)	/	/	Repeat & check from under vehicle	/	/	O/S/R footbrake perform. check	/	/
O/S/F door security/ext. mirror	/	/	Str box rack condition/wear/mtgs	/	/	N/S/R footbrake perform. check	/	/
O/S/F out-in sills/floor/belt mountings	/	/	Ball joints condition/wear/play	/	/	Both rear brakes comparison check	/	/
O/S/R door security/rear back rest	/	/	Track rods-steer arm cond/security	/	/	Exhaust emission (last or first) ◆	/	/
O/S/R out-in sills/floor/belt mountings	/	/	O/S/F tyre wall/fit/tread	/	/			

◆ ENGINE RUNNING	■ FOOTBRAKE APPLIED	● JACKING BEAM IN USE	READINGS OBTAINED			
☒ BEFORE COMPLETION PLEASE READ NOTES OVERLEAF			CO% TEST 1	FRONT	NEAR SIDE 259	OFF SIDE 261
			HC TEST 1	REAR	NEAR SIDE 176	OFF SIDE 210
			CO% TEST 2	PARK	NEAR SIDE 140	OFF SIDE 141
			HC TEST 2			

THE EXAMINER SHOULD NOTE THAT THE VEHICLE MUST PASS TO M.O.T. STANDARD IN ADDITION TO THE OTHER ITEMS LISTED ON THIS INSPECTION REPORT

NOTES FOR GUIDANCE

- | | |
|--|--|
| <p>15 Saloon and hatchbacks must be fitted with 3 rear seatbelts. People carriers etc must have a belt for every seat.</p> <p>18 The vehicle should have 4 doors and boot or rear tailgate. All doors and windows should work correctly.</p> <p>19 The fire extinguisher should be readily available for use in emergency and of a suitable type.</p> <p>22 The First Aid Kit should contain suitable items for use by passengers.</p> <p>23 The body interior including the boot should be in a clean condition with the seats and floor properly covered and maintained fit for public service.</p> <p>24 The Hackney plate number must be displayed inside the vehicle (on tariff card)</p> | <p>25 A meter must be fitted and display the correct tariff 1, 2 and 3. A copy of the current tariffs is attached. It should be checked over a measured distance and time.</p> <p>26 A tariff sheet must be displayed and clearly visible to passengers.</p> <p>27 The body exterior should be free from damage and in a clean condition.</p> <p>28 A roof sign must be displayed.</p> <p>55 The Hackney plate must be fixed to the outside rear of the vehicle on, above or below the bumper and must not be defaced or illegible.</p> <p>56 Advertising is allowed on the front doors only. Maximum size must not exceed 70cm x 35cm.</p> |
|--|--|

NB As from 1 July 2007 'No Smoking' signs should be displayed to comply with The Health Act (2006).

Vehicle Examiner must complete details of meter fitted in vehicle

Make		Model		Serial No	
------	--	-------	--	-----------	--


MOT EXPIRY DATE (Note: all Hackney Carriages over 12 months old must have a current MOT)	Certificate No.	Date of Issue
--	-----------------	---------------

**FOR OTHER ADVICE PLEASE TELEPHONE EAST DEVON DISTRICT COUNCIL LICENSING OFFICE
ON 01395 517411 OR 517410**

CERTIFICATE

I HEREBY CERTIFY that I am an authorised Department of Transport Tester/Inspector and I have carried out the various examinations of the vehicle schedule overleaf and found the vehicle to be safe, comfortable and in sound mechanical condition.

I have also checked the fare meter over the prescribed distances as shown in the table of fares.

Signed*: 	Date: 16/05/18
--	--------------------------

*Authorised to sign Department of Transport Test Certificates

Name in BLOCK CAPITALS MRS S C LEWIS	Vehicle Testing Station No: V108653
--	---

Name of Garage Sowton Mot s 01392 365511	AUTHENTICATION STAMP Sowton Mot s 01392 365511
--	--

Telephone No: 01392 365511

