

E

# P & R Auto's



Rath Na Ri, Clyst Honiton, Exeter, EX5 2HR  
01392 366175 - 07970 410476

## VEHICLE EXAMINATION REPORT

### YOUR ATTENTION IS DRAWN TO THE TERMS AND CONDITIONS BELOW

The examination of the vehicle described in this report was of a purely external, visual nature and excludes any dismantling. No responsibility can be accepted for defects not visibly present at the time, or those not detected which fall outside the scope of the examination and (where possible) its limited road test. Road tests, when possible, are conducted for a limited duration and exclude high speed testing.

The accuracy of the instrumentation within the vehicle (speedometer, odometer, fuel and temperature gauges etc.), cannot be verified, neither can the future life expectancy of the clutch and brake linings, or the failure of mechanical components in the future. Statements on fuel and oil consumption levels will also be excluded.

Report No: PR0076	Inspection Date: 18/04/2025
Customer Details 	Inspection Address <b>Rath Na Ri</b> <b>Clyst Honiton</b> <b>Exeter</b> <b>Devon</b> <b>EX5 2HR</b>
Telephone: 	Telephone: 07967 410476

### VEHICLE DETAILS

Make & Model	VW Caravelle	Registration No.	
Colour	Black	Engine CC	1968 (approx)
Vehicle Identity Number. (VIN No.)			Confirmed Yes
Engine No:	CFCA098168		
V5 Registration doc checked	NO	MOT Certificate Expires	12.4.2026
Odometer Reading	139258 MILES	Service Records Seen	NO

### MECHANIC SUMMARY

### PLEASE READ ALL THE PAGES OF THE REPORT

Vehicle in great condition with low mileage for age.

# P & R Auto's


Rath Na Ri, Clyst Honiton, Exeter, EX5 2HR  
01392 366175 - 07970 410476

## EXTERIOR PANELS

### KEY:

- A acceptable
- G good
- R repaired
- = scratch
- X dent
- C corrosion
- O chip / rust
- D decals
- P poor condition
- not checked

TAXI Colour: Silver



Minor blemishes, which are acceptable for the vehicle's age and type, are not recorded and you should satisfy yourself in this regard.

### EVIDENCE OF BODYWORK REPAIRS

NO No Major Repairs seen

### Comments

### KEY FOR POINTS ON FOLLOWING PAGES

- S Satisfactory for age and recorded mileage
- Could not be checked
- X Needs immediate attention
- A Advisable repair
- N/A Not applicable
- Y Yes
- N No
- C See Engineer's comments

## BODY EXTERIOR

P & R Autos  
Rath Na Ri  
Clyst Honiton  
Exeter  
EX5 2HR  
01392 366175

# P & R Auto's

**Rath Na Ri, Clyst Honiton, Exeter, EX5 2HR**  
**01392 366175 - 07970 410476**

## **ELECTRICAL / CONTROLS**

37. Starting system/Ignition lock	S	43. Stop lights	S	51. Horn	S
38. Battery charging system	S	44. Indicator/Hazard lights	S	52. Radio/Cass./CD/Aerial	S
39. Voltages at battery: normal	S	45. Reverse / Fog lights	S	53. Heater(s) / Fan controls	S
charging	S	46. Auxiliary lights	S	54. Air Con operation	S
40. Headlights	S	47. Interior / Panel lights	S	55. Door locking	S
41. Sidelights /Running lights	S	48. Screen dimisters SELECT	S	56. Windows	S
42. Rear and No. plate lights	S	49. Mirrors (electric)	S	57. Wipers/Washers	S
		50. Controls/Instruments	S	58. Headlamp washers	S
1. Panel Condition/Alignment	S	5. Bumpers No plates – F/R	S	9. Body damage	N
2. Paintwork	S	6. Door locks – operation	S	10. Corrosion	S
3. Exterior trim	S	7. Fuel filler cover and cap	S	11. Mud flaps	S
4. Glass	S	8. Elevating Roof (operation/cond..)	S	12.	

## **ENGINE COMPARTMENT Diesel**

13. Coolant Level/Condition	S	21. Clutch Fluid	S	29. Accelerator linkage	S
14. Coolant leaks	NO	22. Brake Fluid	S	30. Body panels	S
15. Antifreeze	S	23. Engine Oil level	S	31. Bonnet catch	S
16. Radiator/Cap	S	24. External leaks (engine)	NO	32. Bonnet hinges	S
17. Hoses/Pipes	S	25. Engine mountings	S	33. Cold starting	S
18. Drive Belts	S	26. Fuel Injection	S	34. Fast idle (cold)	S
19. Water Pump	S	27. Turbocharger	S	35. Noise level (cold)	S
20. Power Steering	S	28. Fuel pump/Pipes	S	36. Excess fumes/smoke	NO

Spark plugs, Injectors or Glow Plugs are not removed.

It should be noted that a gas analyser has not been used to check exhaust emissions.

If no documentation is seen indicating camshaft drive belt replacement, to ensure future serviceability, it is important that the belt is replaced immediately and then at intervals specified by the manufacturer. It is in your best interests that you ensure that this is carried out.

## **INTERIOR / LUGGAGE COMPARTMENT**

59. Steering Wheel/Adjustment	S	66. Door seals /hinges	S	73.Rear parcel shelf/blind	N/A
60. Seat upholstery – F/R	S	67. Interior sills	S	74. Boot/tailgate lock	S
61. Seat adjustment	S	68. Headlining/visors	S	75. Luggage/Load area trim con	S
62. Seatbelts – F/R	S	69. Sun roof(s)	S	76. Illumination light	S
63. Carpets – F/R	S	70. Dash panel (condition)	S	77. Tool kit etc	S
64. Door trim panels	S	71. Cigarette lighter(s)	S	78. Living Area (Visual Only)	N/A
65. Door fitting /operation	S	72. Mirrors (internal)	S	79.	

## **FRONT SUSPENSION / STEERING / UNDERFRAME**

80. Engine underside leakage	NO	85. Wheel hubs/bearings	S	90. Sub-frames/mountings	S
81. Steering joints/ball joints	S	86. Springs/suspension units	S	91. Suspension arms/mountings/joint	S
82. Steering Rack and Pinion	S	87. Sphrers/Pipes/Hoses	N/A	92. Tie bars/anti roll bars	S
83. Chassis members	S	88. Dampers (condition / leaks)	S	93. Corrosion protection	S
84. Power steering Hydraulic	S	89. Power steering pipes/gaiters	S	94. Corrosion – floor/chassis	NO

## **REAR SUSPENSION / UNDERFRAME**

95. Springs/suspension bars	S	99. Location rods/fixings	S	103. Sub-frames/mountings/axles	S
-----------------------------	---	---------------------------	---	---------------------------------	---

# P & R Auto's

**Rath Na Ri, Clyst Honiton, Exeter, EX5 2HR  
01392 366175 - 07970 410476**

96. Anti roll bar	<b>S</b>	100. Bump stops/gaiters	<b>S</b>	104. Chassis members	<b>S</b>
97. Dampers/bushes	<b>S</b>	101. Wheel hubs/bearings	<b>S</b>	105. Corrosion protection	<b>S</b>
98. Suspension arms/fixings	<b>S</b>	102. Spheres/Pipes/Hoses	<b>N/A</b>	106. Corrosion – floor/chassis	<b>NO</b>
<b>CLUTCH / TRANSMISSION AUTO</b>					
107. Fluid/Oil leaks	<b>NO</b>	111. Casings/Axles/Differential(s)	<b>S</b>	115. Backlash	<b>S</b>
108. Cables/adjustments	<b>S</b>	112. Mountings	<b>S</b>	116. Gaiters	<b>S</b>
109. Hydraulic system	<b>S</b>	113. Drive shaft assembly	<b>S</b>	117. Propeller shaft(s)	<b>S</b>
110. Linkage (wear)	<b>S</b>	114. Universal/sliding joints	<b>S</b>	118. Prop.Bearings/Supports	<b>S</b>

<b>EXHAUST SYSTEM</b>					
119. Manifold(s)	<b>S</b>	121. Silencer(s)/Catalyst(s)	<b>S</b>	123. Joints/Couplings	<b>S</b>
120. Pipes	<b>S</b>	122. Heat shields/Mountings	<b>S</b>	124. System condition	<b>GOOD</b>

<b>FUEL SYSTEM</b>					
125. Tank	<b>S</b>	127. Fuel lines	<b>S</b>	129. Evidence of leaks	<b>NO</b>
126. Tank fixings	<b>S</b>	128. Breather pipes	--	130.	<b>N/A</b>

<b>BRAKES</b>					
131. Master cylinder security	<b>S</b>	134. Flexible hoses	<b>S</b>	137. Hand/Parkbrake op/adjustment	<b>S</b>
132. Fluid leaks	<b>S</b>	135. Pipes/Connections	<b>S</b>	138. Hand/Parkbrake linkage	<b>S</b>
133. Servo/Power system	<b>S</b>	136. Discs/Pads/Drums	<b>S</b>	139. Pedal/Linkage	<b>S</b>

<b>WHEELS AND TYRES Type</b>					
140. Wheel Rims	<b>S</b>	Alloy			
141. Wheel Trims	<b>S</b>				
Tyres	Make	Size	Type / Construction	Min tread depth	
142. RH Front	Michelin	235/50/18	Radial/Tubeless	6-7mm	<b>S</b>
143. LH Front	Michelin	235/50/18	Radial/Tubeless	6-7mm	<b>S</b>
144. RH Rear Inside	Continental	235/50/18	Radial/Tubeless	6-7mm	<b>S</b>
145. RH Rear	Continental	235/50/18	Radial/Tubeless	6-7mm	<b>S</b>
146.					
147.					
148. Spare					<b>N/A</b>

<b>ROAD TEST</b>					
Finish Odom. Reading	<b>139264 MILES</b>		Conditions	Dry	
Test Duration	5.7 Miles		Speed achieved up to 60 M.P.H.		

149. Final drive op./Noise level	<b>S</b>	156. Instrument/Controls function	<b>S</b>	163. Road holding/Stability	<b>S</b>
150. Gearbox operation/noise level	<b>S</b>	157. Steering wheel alignment	<b>S</b>	164. General steering/Handling	<b>S</b>
151. Engine performance	<b>S</b>	158. Clutch operation	<b>S</b>	165. Footbrake operation	<b>S</b>
152. Engine noise	<b>S</b>	159. 4WD operation	<b>N/A</b>	166. Hand/Parkbrake operation	<b>S</b>
153. Excess smoke	<b>NO</b>	160. Cooling fan operation	--	167. Suspension noise	<b>S</b>
154. Overheating evidence	<b>NO</b>	161. Steering effort	<b>S</b>	168. Warning lights	<b>S</b>
155. Auto changes/Kickdown/Inhib.	<b>S</b>	162. Hot restarting	<b>S</b>	169.	

# 5 P & R Auto's

Rath Na Ri, Clyst Honiton, Exeter, EX5 2HR  
01392 366175 - 07970 410476

## FINAL CHECK

170. Oil leaks	NO	171. Coolant leaks	NO	172.
----------------	----	--------------------	----	------

Please read all pages of this report

# **P & R Auto's**

**Rath Na Ri, Clyst Honiton, Exeter, EX5 2HR  
01392 366175 - 07970 410476**

## **Essential & Desirable Repairs**

**It is strongly advised that the essential defects are investigated immediately or rectified prior to purchase of the vehicle and desirable repairs are carried out in the near future. Some defects may prove costly to rectify and this must be considered prior to purchase or authorising any remedial work.**

### ***Attention***

Some vehicles are provided with a master key, which can be extremely costly to replace (sometimes in excess of £1000) as, in some cases, if the master key is missing the Engine Control Unit (ECU) may have to be replaced should you encounter problems. As well as this, some radios have codes to allow them to operate. Please satisfy yourself that you have all relevant keys and codes. You should also ensure you are given all relevant instruction manuals for the vehicle, radio, alarm and immobilisers as necessary

Item	Defect/Item requiring further investigation /rectification	D/X

Report Ref:	Reg. No:		Mechanics Name:	Date:
PR076				18/04/2025