

APPENDIX C

MOT test certificate



Driver & Vehicle
Standards
Agency

① Vehicle identification number

[REDACTED]

②a Registration number

[REDACTED]

②b Country of registration

GB

Make and model

SEAT ALHAMBRA

⑤ Vehicle category

④ Mileage

135,999 miles

Mileage history

126,914 miles 06.02.2025

113,622 miles 13.02.2024

103,546 miles 15.02.2023

⑦ **Pass**

⑥a Date of the test

23.02.2026

⑥b Expiry date

22.02.2027

To preserve the anniversary of the expiry date, the earliest you can present your vehicle for test is 23.01.2027.

③a Location of the test

[REDACTED]

③b Testing organisation and inspector name

[REDACTED]

MOT test number

[REDACTED]

Check that this document is genuine by visiting www.gov.uk/check-mot-history

If any of the details are not correct, please contact DVSA by email at enquiries@dvsa.gov.uk or by telephone on 0300 1239000.

Receive a free annual MOT reminder by subscribing at www.gov.uk/mot-reminder or by telephone on 0300 1239000.

Issuer signature

SEAT ALHAMBRA

[Check another vehicle](#)

Colour
Silver

Fuel type
Diesel

Date registered
29 March 2016

MOT valid until
22 February 2027

[Get an MOT reminder](#) by email or text.

[Download test certificates](#)

You can [get information corrected on your MOT history](#) (such as mileage or vehicle details) if it's wrong.

[Hide all sections](#)

MOT history

Check mileage recorded at test, expiry date, and test outcome

[Hide](#)

Date tested
23 February 2026

Mileage
135,999 miles

MOT test number

PASS

Test location

[View test location](#)

Expiry date
22 February 2027

Date tested
20 February 2026

Mileage
135,998 miles

MOT test number

FAIL

Test location

[View test location](#)

Do not drive until repaired (dangerous defects):

- **Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**

Repair immediately (major defects):

- **Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**
- **Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**

Date tested
6 February 2025

PASS

Mileage
126,914 miles

Test location

▶ [View test location](#)

MOT test number

Expiry date
22 February 2026

Date tested
13 February 2024

PASS

Mileage
113,622 miles

Test location

▶ [View test location](#)

MOT test number

Expiry date
22 February 2025

Date tested
15 February 2023

PASS

Mileage
103,546 miles

Test location

▶ [View test location](#)

MOT test number

Expiry date
22 February 2024

Date tested
15 February 2023

FAIL

Mileage
103,545 miles

Test location

▶ [View test location](#)

MOT test number

Do not drive until repaired (dangerous defects):

- Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Date tested
23 February 2022

PASS

Mileage
93,096 miles

Test location

▶ [View test location](#)

MOT test number

Expiry date
22 February 2023

Date tested
22 February 2022

FAIL

Mileage
93,095 miles

Test location

▶ [View test location](#)

MOT test number

Do not drive until repaired (dangerous defects):

- Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Date tested
16 February 2021

PASS

Mileage
76,855 miles

Test location

▶ [View test location](#)

MOT test number

Expiry date
20 February 2022

Monitor and repair if necessary (advisories):

- **Front Brake disc worn, but not excessively (1.1.14 (a) (i))**
- **Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**
- **Nearside Rear Nail in tyre**

▶ [What are advisories?](#)

Date tested
21 February 2020

PASS

Mileage
61,186 miles

Test location

▶ [View test location](#)

MOT test number

Expiry date
20 February 2021

Date tested
18 February 2020

FAIL

Mileage
61,183 miles

Test location

▶ [View test location](#)

MOT test number

Repair immediately (major defects):

- **Fuel tank leaking (6.1.3 (b) (i))**
- **Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**
- **Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**

Date tested
20 March 2019

PASS

Mileage
48,409 miles

Test location

▶ [View test location](#)

MOT test number

Expiry date
30 March 2020

Monitor and repair if necessary (advisories):

- **Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**

Date tested
20 March 2019

FAIL

Mileage
48,409 miles

MOT test number

Test location

▶ [View test location](#)

Repair immediately (major defects):

- **Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**
- **Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**

Monitor and repair if necessary (advisories):

- **Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**
- **Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**

The MOT test changed on 20 May 2018

Defects are now categorised according to their severity - dangerous, major, and minor. [Find out more.](#)

Date tested
19 March 2018

PASS

Mileage
31,322 miles

MOT test number

Test location

▶ [View test location](#)

Expiry date

30 March 2019

Advisory notice item(s)

- **Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**
- **Front Brake pad(s) wearing thin (3.5.1g)**

Date tested
31 March 2017

PASS

Mileage
15,755 miles

MOT test number

Test location

▶ [View test location](#)

Expiry date

30 March 2018

Advisory notice item(s)

- **Offside Front Tyre worn close to the legal limit (4.1.E.1)**
- **Offside Rear Nail in tyre**